FIELD REPORT

(3)

DELLA PENNA ENGINEERING, INC.
21 Whitetail Lane
Parkesburg, PA 19365
TEL: 610-857-0045 FAX: 610-857-0046

DATE 6/30/2010	REPORT NO. 1178
PROJECT Manchester Farms - Lot 67	
LOCATION East Fallowfiled Township	
CONTRACTOR Dave Thomas	OWNER Dewey Homes
WEATHER	TEMP °at AM °at PM
PRESENT AT SITE Contractor	

To East Fallowfield Township

RECEIVED
AUG 03 2010
BY: BM

THE FOLLOWING WAS NOTED:

Contractor had dug bed in rear of yard and pit measured approximately 16'x41'. Fabric was in place and 2'x2' concrete yard drain was on-site. Bed was slightly over 36" deep. Silt fence was in place.

7/1 - AM -Yard drain was set, stone had been placed and contractor was installing pipe. Remainder of stone would then be placed.
PM - Bed backfilled and area around bed was being graded. Checked grades to make sure surface pitches to yard drain. Contractor attempting to reshape berm top make it more subtle but still keep water on property and direct it into yard drain. Neighbor to the north (Lot 68 - Jason Vernon) said they want all extra dirt and would mark a spot to pile it. Landscapers supposed to come in to finish off work.

Bed checked again after work was completed. Sod had been installed over whole area however some additional areas still need sod. Homeowner was watering sod continuously and it appeared to be doing well. Some minor settlement near yard drain may need to be filled.

Checked site again after heavy rain and water was above level of yard drain but was draining. Fabric was still in place under yard drain grate to keep sediment out of bed and was probably slowing draining of surface water into bed. Will contnue to monitor bed. Did not appear that any runoff had overflowed onto downhill neighbor.

COPIES TO
Dewey Homes, Dave Thomas

SIGNED