FIELD REPORT

DELLA PENNA ENGINEERING, INC.
21 Whitetail Lane
Parkesburg, PA 19365
TEL: 610-857-0046 FAX: 610-857-0046

DATE 5/12/2010	REPORT NO. 1170
PROJECT Fieldstone Village	
LOCATION East Fallowfield Twp.	
CONTRACTOR	OWNER DeLuca Homes
WEATHER Rain	TEMP °at AM / °at PM
PRESENT AT SITE	

To East Fallowfield Township

RECEIVED
MAY 19 2010
BY: Denise McCleer

THE FOLLOWING WAS NOTED:

Checked E&S controls just after haevy rains. Sediment traps 1 & 2 were drained and appeared to be functioning as designed. Outlet pipe from Sediment trap 2 was repaired but could not be checked for leaks since water level was below top of pipe.

Skimmer head in Sediment Basin 1 was completely disconnected from pipe. Water was flowing unrestricted through outlet pipe and out to Oaklyn Road. Skimmer head must be reinstalled ASAP and securely fastened.

COPIES TO
DeLuca Homes, Bulldog

SIGNED