3930-FM-WM0092 Rev. 2/2011

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF WATERSHED MANAGEMENT

EARTH DISTURBANCE INSPECTION REPORT

Project Name Pelham Place aka Field Stone **Inspection Date** 12/05/12 **Report No.** 2012-39

Weather Conditions Sunny and brisk **Time of Inspection** 1:45 p.m.

Location S Caln Rd. **Total Project Area** 104 **Total Disturbed Area** 39.5

Municipality E Fallowfield Twp **County** Chester

Receiving Water(s) UNT to W Branch Brandywine Creek **Designated/Existing Use** EV

Responsible Party(s) Longview Fieldstone, LP

(name & address) 1055 Westlakes Drive, Suite 170

Berwyn, PA 19312

Phone

Site Representative (name)

(title)

Inspector (name) Gordon Roscovich

(title) Chester County Conservation District

Type of Inspection (check only one)

Routine complete ☐ Routine partial ☒ Follow-up ☐ Complaint ☐ Final ☐

Photographs Taken Yes ☒ No ☐

Site Description & Observations:

For this inspection it was observed that the materials and equipment for the installation of the infiltration bed were on-site and staged for installation in addition to a pallet of filter socks. The area where the infiltration bed is to be installed was staked out and had the vegetative cover cleared. Perimeter controls should be installed and maintained for the duration of the earth disturbance activities.

The following violation was noted:

1) Failure to implement effective Best Management Practices (BMPs) (i.e. filter socks should be installed downslope of earth disturbance activity).

☐ **Continued on page 3**

Permit and Plan Requirements			Type of Activity (check as many as appropriate)			
Y	N					
☒	☐	Written Erosion & Sediment Control Plan required			☐	Other
☒	☐	Written Post Const. Stormwater Management Plan required	☐	Pub. Road Constr./Maint. (PRC)	☐	Pvt. Road/Residence (PRRS)
☐	☒	Erosion & Sediment Control Plan requested	☒	Res. Subdivision (RSBD)	☐	Comm./Indust. Dev. (CMIN)
☐	☒	Post Construction Stormwater Management Plan requested	☐	Govmt. Facilities (GOV)	☐	Recreation Facilities (RECF)
☐	☒	E & S Permit required	☐	Utilities Facilities (UTL)	☐	Agricul. Activities (AGA)
☒	☐	NPDES Permit required	☐	Sewer/Water Systems (SWS)	☐	Pipeline
		☐ Phased Constr. ☒ Non-Phased Constr.	☐	Remediation/Restoration (RRES)	☐	Silviculture (SILV)

Permit #: PAI011501003 **Exp. Date:** April 27, 2015

3930-FM-WM0092a Rev. 2/2011

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF WATERSHED MANAGEMENT

EARTH DISTURBANCE INSPECTION REPORT

Project Name Pelham Place aka Field Stone **Inspection Date** 12/05/12 **Report No.** 2012-39

Inspection Findings (check as many as appropriate)		**Reference**
1.	No violations observed at this time:	☐ (N/A)
2.	Failure to (check all that apply):	
a.	Develop a written Erosion and Sediment Control Plan:	☐ (102.4)
b.	Have an Erosion and Sediment Control Plan available on site:	☐ (102.4)
c.	Submit Erosion and Sediment Control Plan as requested:	☐ (102.4)
d.	Implement effective Best Management Practices (BMPs):	☒ (102.4)
e.	Maintain effective E & S Best Management Practices:	☐ (102.4)
f.	Use Antidegradation Best Available Combination of Technologies (ABACT) BMPs for Discharges to High Quality or Exceptional Value Waters:	☐ (102.4)
g.	Obtain an NPDES Permit for Stormwater Discharges Associated With a Construction Activities:	☐ (102.5)
h.	Obtain an Erosion and Sediment Permit:	☐ (102.5)
i.	Prepare and implement a PPC Plan:	☐ (102.5)
j.	Submit Notice of Termination:	☐ (102.7)
k.	Develop written Post Construction Stormwater Management (PCSM)Plan:	☐ (102.8)
l.	Have PCSM Plan available on site:	☐ (102.8)
m.	Submit Post Construction Management Plan as requested:	☐ (102.8)
n.	Implement effective PCSM BMPs:	☐ (102.8)
o.	Maintain effective PCSM BMPs:	☐ (102.8)
p.	Perform reporting and recordkeeping as required:	☐ (102.8)
q.	Implement riparian buffer or riparian forest buffer:	☐ (102.14)
r.	Meet regulatory requirements for riparian forest buffer:	☐ (102.14)
s.	Provide temporary stabilization of the earth disturbance site	☐ (102.22)
t.	Provide permanent stabilization of the earth disturbance site:	☐ (102.22)
u.	Comply with permit conditions:	☐ (402CSL)
3.	Sediment or other pollutant was discharged into waters of the Commonwealth:	☐ (401 CSL)
4.	Site conditions present a potential for pollution to waters of the Commonwealth:	☒ (402 CSL)
5..	Other (describe): _____	_____
6.	Other (describe) _____	_____
7.	Other (describe) _____	_____
8.	Other (describe) _____	_____
9.	Other (describe) _____	_____

☒ **Inspection of this project has revealed site conditions which constitute violations of 25 Pa. Code Chapters 92 and/or 102 and the Clean Streams Law, the act of June 22, 1937, P.L. 1987, 35 P.S. §691.1 *et seq.***

Additional information regarding these violations can be found on the back of this page.

3930-FM-WM0092a Rev. 2/2011

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF WATERSHED MANAGEMENT

EARTH DISTURBANCE INSPECTION REPORT

Project Name Pelham Place aka Field Stone **Inspection Date** 12/05/12 **Report No.** 2012-39

Continuation Sheet

Site Description & Observations:

Compliance Assistance Measures:

Continued ☐

Follow-up Inspection will occur on or about (date) January 2013

Sent to Responsible Party	12/06/12	Gordon Roscovich	12/06/12
(Signature of Site Representative)	(Date)	(Inspector's Signature)	(Date)

The Site Representatives' signature acknowledges that they have read the report and received a copy and that they were given an opportunity to discuss it with the inspector. The signature does not necessarily mean the signee agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF WATERSHED MANAGEMENT

This report is official notification that a representative of the Department of Environmental Protection has conducted an inspection of your earth disturbance activity to determine compliance with Title 25, Chapter 92, National Pollutant Discharge Elimination System, Title 25, Chapter 102, Erosion and Sediment Control, and the Pennsylvania Clean Streams Law. This representative may be an employee of the local County Conservation District, which by delegation agreement with the Department of Environmental Protection, is authorized to investigate complaints, inspect earth disturbance activities and conduct compliance actions. Any violations observed by the Department/Conservation District have been noted on this report form and constitute unlawful conduct as defined in Section 611 of the Clean Streams Law.

There will be no written confirmation of those violations from the Department. Failure to take corrective actions to resolve the violations may result in administrative, civil and/or criminal penalties being instituted by the Department of Environmental Protection as defined in Section 602 of the Clean Streams Law of Pennsylvania. The Clean Streams Law provides for up to $10,000 per day in civil penalties, up to $10,000 in summary criminal penalties, and up to $25,000 in misdemeanor criminal penalties for each violation.

This report does not constitute an Order or appealable action of the Department. Nothing contained herein shall be deemed to grant or imply immunity from legal action for any violation noted herein.

For further information or assistance please contact:

Chester County Conservation District
688 Unionville Road, Suite 200
Kennett Square, PA 19348
Phone- (610) 925-4920
Fax - (610) 925-4925
www.chesco.org/conservation

cc: E Fallowfield Township (e-mail)
Chris Dell Penna (e-mail)
John Penders & Greg Graham (Rouse Chamberlin)
Frank DeFrancesco (PA DEP Compliance Specialist)
Project File